

13 PIN VEHICLE HEADLIGHT ADAPTER CHART

	VEHICLE	SYSTEM TYPE	CONFIGURATION	HEADLIGHT/BULB	PART NO.
CHEVY/GMC	1980 - 2006 Chevy/GMC	2 Lamp Rectangular Sealed Beam		6052 or H6054 (2B)	MSC04599
	1980 & Older Chevy/GMC	2 Lamp Round Sealed Beam		6014 or H6017 (2B)	MSC04599
	1987 & Older Chevy/GMC	4 Lamp Sealed Beam		High Beam 4651 or H4651 (1A) Low Beam 4652 or H4656 (2A)	MSC04599
	1988-1989 Chevy/GMC	4 Lamp Sealed Beam		High Beam H4701 (LF) Low Beam H4703 (UF)	MSC04600
	1990 - 2000 Chevy/GMC (Classic Body Style)	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC04601
	1999 - 2006 Chevy/GMC 1500, 2500 & 3500	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC04601
	2007 Chevy/GMC (Classic Body Style)	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC04601
	2007 - 2014 Chevy/GMC 2500 & 3500	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam (H11)	MSC09003
	2007 - 2013 Chevy/GMC 1500	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam (H11)	MSC09003
	2014 & Newer Chevy/GMC 1500	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam (H11)	MSC09044
	2015 & Newer Chevy/GMC 2500 & 3500	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam (H11)	MSC09044
	2015 & Newer Chevy/GMC 2500 & 3500	2 Lamp Replaceable Bulb		9012 (HIR-2)	MSC09044
	2007 - 2013 Yukon	2 Lamp Replaceable Bulb		9008 (H13)	MSC09993
	2007 - 2014 Chevy/GMC	2 Lamp Sealed Beam		6052 or H6054 (2B)	MSC04599¹
	2003 - 2010 C4500/C5500	2 Lamp Sealed Beam		H4651 (2B)	MSC09809
	2004 - 2013 Colorado/Canyon	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC04601
FORD	1980 - 1986 Ford	2 Lamp Sealed Beam		H6054 (2B)	MSC04599
	1987 - 1991 Ford	2 Lamp Replaceable Bulb		9004 (HB1)	NONE REQUIRED
	1992 - 2003 F150	2 Lamp Replaceable Bulb		9007 (HB5)	NONE REQUIRED
	2004 - 2008 F150	2 Lamp Replaceable Bulb		9008 (H13)	MSC08839
	2009-2010 & 2013-2015 F150	2 Lamp Replaceable Bulb		9008 (H13)	MSC09993
	2013 & Newer F150	HID			MSC09041
	1998 - 2012 Ranger	2 Lamp Replaceable Bulb		9007 (HB5)	NONE REQUIRED
	1992 - 2004 F250, F350, Super Duty & Excursion	2 Lamp Replaceable Bulb		9007 (HB5)	NONE REQUIRED
	1999 - 2007 Super Duty	2 Lamp Sealed Beam		H6054 (2B)	MSC04599
	2005 - 2007 Super Duty & Excursion	2 Lamp Replaceable Bulb		9008 (H13)	MSC08839
	2008-2015 Super Duty	2 Lamp Sealed Beam		H6054 (2B)	MSC04599¹
	2008-2015 Super Duty & Excursion	2 Lamp Replaceable Bulb		9008 (H13)	MSC09993
	2000-2014 F650/750	2 Lamp Replaceable Bulb		9003 (H4)	MSC06409
	1991-1993 Dodge Ram	2 Lamp Sealed Beam		6052 or H6054 (2B)	MSC04599
DODGE	1994 - 1998 Dodge Ram	2 Lamp Replaceable Bulb		9004 (HB1)	NONE REQUIRED
	2000 - 2004 Dakota 2000 - 2003 Durango	2 Lamp Replaceable Bulb		9007 (HB5)	NONE REQUIRED
	1999 - 2001 Ram 1/2 Ton (Without Sport Package)	2 Lamp Replaceable Bulb		9004 (HB1)	NONE REQUIRED
	1999 - 2001 Ram 1/2 Ton (With Sport Package)	4 Lamp Replaceable Bulb		9004 / 9007 (HB1/HB5)	MSC04597
	1999 - 2002 Ram 3/4 & 1 Ton (Without Sport Package)	2 Lamp Replaceable Bulb		9004 (HB1)	NONE REQUIRED
	1999 - 2002 Ram 3/4 & 1 Ton (With Sport Package)	4 Lamp Replaceable Bulb		9004 / 9007 (HB1/HB5)	MSC04597
	2002 - 2005 Ram 1/2 Ton	2 Lamp Replaceable Bulb		9007 (HB5)	NONE REQUIRED
	2003 - 2005 Ram 3/4 & 1 Ton	2 Lamp Replaceable Bulb		9007 (HB5)	NONE REQUIRED
	2006 - 2015 Ram 1/2, 3/4 & 1 Ton	2 Lamp Replaceable Bulb		9008 (H13)	MSC09993
	2009-2015 Ram 1/2, 3/4 & 1 Ton	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam (H11)	MSC09993
	2013-2015 Ram 1/2, 3/4 & 1 Ton	4 Lamp Projector Beam		High Beam 9005 Low Beam HIR2	MSC09346
	2008-2015 Ram 4500/5500	2 Lamp Replaceable Bulb		9008 (H13)	MSC09993
INTERNATIONAL	2002-2014 DuraStar / TerraStar	2 Lamp Replaceable Bulb		No direct bulb connection	MSC06428²
	2008-2010 Bullet 4500/5500	2 Lamp Replaceable Bulb		9008 (H13)	MSC09993
JEEP	1997-2002 Jeep Wrangler	2 Lamp Sealed Beam		H6024	MSC04599
	2007 - 2015 Jeep Wrangler	2 Lamp Replaceable Bulb		9008 (H13)	MSC09993
MITSUBISHI	1999 - 2004 Mitsubishi FG (4X4)	4 Lamp Replaceable Bulb		46H3 / 46R3 (1A/2A)	MSC04599
	2005 - 2010 Mitsubishi FG (4X4)	2 Lamp Replaceable Bulb		9003 (H4)	MSC09702
NISSAN	2009 - 2015 Frontier	2 Lamp Replaceable Bulb		HB5	NONE REQUIRED¹
	2004 - 2015 Titan	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam 9006 (HB4)	MSC06289
TOYOTA	2005-2015 Tacoma	2 Lamp Replaceable Bulb		9003 (H4)	MSC04599
	2000 - 2006 Tundra	2 Lamp Replaceable Bulb		9003 (H4)	MSC04599
	2007 - 2013 Tundra	4 Lamp Replaceable Bulb		High Beam 9005 (HB3) Low Beam (H11)	MSC05665
	2014-2015 Tundra	2 Lamp Replaceable Bulb		9003 (H4)	MSC04599¹

¹ Turn Signal Relay Kit MSC09991 will be required in addition to Headlight Adapter MSC04599

² This headlight adapter is connected to a junction in the truck harness. It does not connect directly to the back of the bulb.